

All Saints closed Churchyard

Risk assessment as compiled by the Responsible Financial Officer who is the lead for all Saints Churchyard on Bradgate Road.

The Parish Council employ an outside company for ground maintenance during the growing season

The Churchyard is closed to Burials but not the interment of Ashes. The gravestones, mostly slate are checked regularly for stability. In 2017 a number of gravestones were found to be unstable and steps are being taken to apply for a Faculty to stand these around the walls of the churchyard.

The drystone walls surrounding the Church and Churchyard are regularly checked and if necessary repaired by a qualified stonemason.

The Lychgate is regularly checked and was fully refurbished in 2001.

The manhole cover on the path at the side of the Church was replaced in 2001.

The path leading to the Church and encircling it is regularly checked for moss and removed as and when necessary.

The Parish Council has a mandatory cover for public liability of not less than £10 million

Signed.....

Signed.....

Dated.....